

TEST REPORT

No. : SHIN2408002054CM01_EN

Date : 2024-08-30

Page: 3 of 3

Test Item: Castor Chair Test

Test Method: ISO 4918:2016/Amd.1:2018

Test Condition:

Specimen: $\Phi 750\text{mm} \times 7.5\text{mm}$, 1pc

Load: 90kg

Type of wheels: Type W

Cycles: 25000r

Type of specimen: Resilient floor coverings

Lab Environmental Condition: $(23 \pm 2)^\circ\text{C}$, $(50 \pm 5)\% \text{RH}$

Test Result:

Test Item	Test Result
Castor Chair Test	No visible damage

Note: Test specimens were cut from original sample.

The test report shall only be used for clients' scientific research, teaching, internal quality control, product research and development, etc... and just for internal reference.

*****End of report*****



Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at <https://www.sgs.com/en/Terms-and-Conditions>. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. Unless otherwise stated the results shown in this test report refer only to the sample(s) tested and such sample(s) are retained for 30 days only.

Attention: To check the authenticity of testing/inspection report & certificate, please contact us at telephone: (86-755) 8307 1443, or email: CN_DocsCheck@sgs.com

No.59, Block 1159, East Kang Qiao Road, Pudong District, Shanghai, China 201319

中国·上海·浦东康桥东路1159弄69号 邮编: 201319

t(86-21) 61196300 www.sgs.com

t(86-21) 61196300 sgs.china@sgs.com

TEST REPORT

No. : SHIN2408002054CM01_EN

Date : 2024-08-30


Page: 2 of 3

Summary of Results:

No.	Test Item	Test Method	Result	Conclusion
1	Castor Chair Test	ISO 4918:2016/Amd.1:2018	See Result	N/A

Note: Pass : Meet the requirements;
 Fail : Does not meet the requirements;
 N/A : Not Apply to the judgment.

Original Sample Photo(s):



Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at <https://www.sgs.com/en/Terms-and-Conditions>. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. Unless otherwise stated the results shown in this test report refer only to the sample(s) tested and such sample(s) are retained for 30 days only.

Attention: To check the authenticity of testing/inspection report & certificate, please contact us at telephone: (86-755) 83071443, or email: CN.Doccheck@sgs.com

No.69, Block 1159, East Kang Diao Road, Pudong District, Shanghai, China 201319

中国·上海·浦东康桥东路1159弄69号 邮编: 201319

t(86-21) 61196300 www.sgs.com.cn

t(86-21) 61196300 sgs.china@sgs.com